

21-153 - Resurfacing of Brookmount and Shady Springs Playground  
 Bid Opening 2:00 PM, Friday, July 23, 2021

All Bids are subject to correction after bids have been completely reviewed



				Fry & Associates		All Inclusive Rec		Innovative Sport Surfacing	
				101 E. 15th Avenue		400 North Washington Street, Ste 224A		8425 Station Street	
				North Kansas City, MO 64116		Farmington, MO 63640		Mentor, OH 44060	
				800-444-9787		886-701-9787		440-205-0875	
				<a href="mailto:sales@fryinc.com">sales@fryinc.com</a>		<a href="mailto:salesupport@allinclusive.com">salesupport@allinclusive.com</a>		<a href="mailto:kristen@innovativesportsurfacing.com">kristen@innovativesportsurfacing.com</a>	
Item	Description	Qty	Unit	Unit Cost	Cost	Unit Cost	Cost	Unit Cost	Cost
1	Materials and Labor to Resurface Shady Springs Playground as specified in Section L	1	LS	\$46,129.00	\$46,129.00	\$47,761.00	\$47,761.00	\$47,190.00	\$47,190.00
2	Materials and Labor to Resurface Brookmount Park Playground as specified in Section L	1	LS	\$44,133.00	\$44,133.00	\$48,101.00	\$48,101.00	\$50,275.00	\$50,275.00
<b>Total Items 1-2</b>				<b>\$90,262.00</b>		<b>\$95,862.00</b>		<b>\$97,465.00</b>	
Resurfacing Installation Option Chosen				Bonded Rubber		Dual Layer Poured-In-Place		Bonded Rubber	

				Innovative Sport Surfacing		All Inclusive Rec		National Playground	
				8425 Station Street		400 North Washington Street, Ste 224A		708 Clearwater Drive	
				Mentor, OH 44060		Farmington, MO 63640		Camdenton, MO 65020	
				440-205-0875		886-701-9787		314-225-7988	
				<a href="mailto:kristen@innovativesportsurfacing.com">kristen@innovativesportsurfacing.com</a>		<a href="mailto:salesupport@allinclusive.com">salesupport@allinclusive.com</a>		<a href="mailto:erniek63040@yahoo.com">erniek63040@yahoo.com</a>	
Item	Description	Qty	Unit	Unit Cost	Cost	Unit Cost	Cost	Unit Cost	Cost
1	Materials and Labor to Resurface Shady Springs Playground as specified in Section L	1	LS	\$48,955.00	\$48,955.00	\$52,371.00	\$52,371.00	\$52,440.00	\$52,440.00
2	Materials and Labor to Resurface Brookmount Park Playground as specified in Section L	1	LS	\$52,166.00	\$52,166.00	\$49,013.00	\$49,013.00	\$49,008.00	\$49,008.00
<b>Total Items 1-2</b>				<b>\$101,121.00</b>		<b>\$101,384.00</b>		<b>\$101,448.00</b>	
Resurfacing Installation Option Chosen				Dual Layer Poured-In-Place		Dual Layer Poured-In-Place		Dual Layer Poured-In-Place	

				Fry & Associates		Fry & Associates		Abcreative LLC	
				101 E. 15th Avenue		101 E. 15th Avenue		33160 W 83rd	
				North Kansas City, MO 64116		North Kansas City, MO 64116		De Soto, KS 66018	
				800-444-9787		800-444-9787		314-489-3242	
				<a href="mailto:sales@fryinc.com">sales@fryinc.com</a>		<a href="mailto:sales@fryinc.com">sales@fryinc.com</a>		<a href="mailto:dana@abcreative.net">dana@abcreative.net</a>	
Item	Description	Qty	Unit	Unit Cost	Cost	Unit Cost	Cost	Unit Cost	Cost
1	Materials and Labor to Resurface Shady Springs Playground as specified in Section L	1	LS	\$53,004.00	\$53,004.00	\$60,791.00	\$60,791.00	\$63,333.00	\$63,333.00
2	Materials and Labor to Resurface Brookmount Park Playground as specified in Section L	1	LS	\$49,807.00	\$49,807.00	\$57,075.00	\$57,075.00	\$60,299.00	\$60,299.00
<b>Total Items 1-2</b>				<b>\$102,811.00</b>		<b>\$117,866.00</b>		<b>\$123,632.00</b>	
Resurfacing Installation Option Chosen				Dual Layer Poured-In-Place		Bonded Rubber		Dual Layer Poured-In-Place	